


P21847.A21



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor/s : Y. NAGATA et al.

Certificate of Correction Branch

Patent No. : 6,831,528 B2

Issued: December 14, 2004

Appl. No. : 10/026,459

Filed: December 27, 2001

For : HIGH-FREQUENCY SWITCHING MODULE AND HIGH-FREQUENCY APPARATUS EQUIPPED WITH THE SAME

COVER LETTER FOR REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner For Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

**Certificate
JUN 17 2005
of Correction**

Sir:

Attached are a Request and a proposed Certificate of Correction in connection with the above-identified patent.

A check in the amount of \$100.00 is enclosed to cover the fee. The Commissioner is hereby authorized to charge any additional fees, or credit any overpayment, to Deposit Account No. 19-0089.

Respectfully submitted,
Y. NAGATA et al.

Bruce H. Bernstein
Reg. No. 29,027

Steven Wegman
Reg. No. 31,438

June 13, 2005
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

JUN 20 2005

P21847.A20



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor/s/ : Y. NAGATA et al.

Certificate of Correction Branch

Patent No. : 6,831,528 B2

Issued: December 14, 2004

Appl. No. : 10/026,459

Filed: December 27, 2001

For : HIGH-FREQUENCY SWITCHING MODULE AND HIGH-FREQUENCY APPARATUS EQUIPPED WITH THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner For Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following error appearing in the printed patent which is apparently the fault of the inventor, as per the attached Certificate of Correction.

On the cover of the printed patent, at Item (56), References Cited, Other Publications, line 1, "7-205502" should be —7-202502—. This appeared correctly in the Information Disclosure Statement filed on April 3, 2002, but was incorrectly listed on the Form PTO-1449 that accompanied the Information Disclosure Statement.

Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:

06/15/2005 JBALINAN 00000053 6831528

01 FC:1811

100.00 OP

1


JUN 20 2005

P21847.A20

On the cover of the printed patent, at Item (56), References Cited, Other Publications, line 1, "7-205502" should be —7-202502—.

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,
Y. NAGATA et al.



Bruce H. Bernstein
Reg. No. 29,027

Steven Wegman
Reg. No. 31,438

June 13, 2005
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**PATENT NO. : 6,831,528 *B2*

DATED : December 14, 2004

INVENTOR(S) : Y. NAGATA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, Other Publications, line 1, "7-205502" should be —7-202502—.

MAILING ADDRESS OF SENDER:

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

PATENT NO. 6,831,528 *B2*

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

JUN 20 2005

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**PATENT NO. : 6,831,528 *b2*

DATED : December 14, 2004

INVENTOR(S) : Y. NAGATA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent
is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, Other Publications, line 1, "7-205502"
should be —7-202502—.

MAILING ADDRESS OF SENDER:

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191PATENT NO. 6,831,528 *b2*

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

JUN 20 2005